

ANNEXURE - 4

ANNEXURE - 4	
S NO	LIST OF HAZARDOUS MATERIALS
1	FORMALDEHYDE SOLUTION
2	POVIDINE IODINE SOLUTION
3	POVIDINE IODINE SCRUB
4	SURGICAL SPIRIT
5	HYDROGEN PERAXIDE
6	SAVLON SOLUTION
7	SODIUM HYPOCHLORIDE